You will need • 10mm spanner

Sometimes it's nescessary to reset the FTO's ECU. The FTO has a very clever engine management system and in the case of the tiptronic model, a memory which 'learns' your driving style. Sometimes however it may become sluggish or the car may idle irratically.

If you are having irratic idling then it may be that you need to clean or replace your **Steppa Motor** but it's a good idea to reset the ECU first before doing this, just to see that it's not the ECU.

It's amazingly easy to do this, all you have to do is disconnect the battery. Yes, it's that simple. Remember to take off the black first, and replace it last and that's it. You have to disconnect the battery and leave the car like that for 30mins or more for the memory to be 'lost'. Then, reconnect and take it for a drive. Some things might be strange till the car re-learns things (ie, idle might even stall the car, gear changes will be in unexpected places on a tip etc).